



FACILITIES SUMMER 2016 UPDATE

- Our team completed over 335 assorted work orders.
- Replacement diffusers and LED lamps were installed on north side of Russell Hall to increase light at night.
- 38 replacement ballasts were installed in Russell Hall
- A leak in sewer line was repaired in Russell Hall.
- The fashion lab reconfigured and the electrical was moved to accommodate new lecture friendly style configuration.
- Installed new flooring, compressed air lines and electrical outlets for new Engineering equipment in A214.
- In A225, data and electrical lines were installed to accommodate desks and installed new white boards. The desks were re-arranged lecture style.
- Created a new faculty office in L-207. Removed old ITS equipment, built cabinet for electrical, painted and installed new carpet. Reorganized data lines to accommodate new desk locations.
- In T107, we installed new compressed air lines for new CNC machines, installed desks, data and electrical for new computers. Removed old floor tile and painted floor in area.
- The following rooms were painted R211, R225, V500, V200, V105, V107, A107. A107-3, A107-7, A107-11, A225, A205, A209 and the Diesel classroom.
- Installed 2 sinks with water heaters in exam rooms in the Village Health center.
- Repaired gym floor and painted new defensive arc lines.
- Replaced entire roof of W building.
- Replaced hot water boiler on roof of W building.
- Replaced "Pour and Play" at SAC CDC and CEC CDC.
- The damaged sod on football field was replaced with GN1 sod.
- Installed electrical in classroom of K-115.
- Installed additional electrical in robotic welding lab and painted the floor.
- Installed a new floor and electrical in B10 for SAUSD.
- Tested generator and UPS systems in A building to troubleshoot an issue that arose after the 14 hour power outage on campus.
- The flooring in A101 was replaced as a result of a leak in a water line in the ceiling.
- Assisted with the removal of all planetarium show lighting to accommodate the new system of LED lamps and their associated controls.
- Repaired significant leak at CJTC. Working on replacing two additional domestic water lines that feed the building.
- Occupational Therapy - Totally remodeled OT lab. Installed new carpet, ceiling tile, paint, cabinets and kitchen.
- The carpets were replaced in B4-B8.
- The hallways were painted in Chavez and I buildings.
- Electrical was installed in hallways of I, A, C and H buildings.