



SAC FACILITIES UPDATE  
February 21, 2017

- Received 266 work orders since 1/1/2017, completed 163, received 91 last week.
- Carpet replaced in H104, H105, H107, H108, H109
- Walls and ceilings painted in H104, H105, H107, H108, H109
- Walls and ceilings painted in R307, R303, R114
- Carpet replaced in R307
- Completely painted interior and exterior of X building.
- Replaced all carpet in X building
- Hydration stations installed in F and H buildings
- Installed 36 whiteboards in I building
- Repaired water leaks in R, J and K building complexes
- All roofs checked for leaks, gutters cleaned.
- All storm drains cleaned
- Repaired major storm drain break in CDC.
- Tested and serviced generator to prepare for SoCal Edison shutdown. (completed shutdown and re-energizing of campus).
- Tested all fire alarms at SAC, DMC, CEC and Academy. All repairs made.
- Serviced all fire extinguishers and replaced all out of service and expired units.
- Assisting with coordination of new energy management system in all buildings not effected by Central plant.
- Repaired gas leak outside Russell Hall in under sidewalk.
- Completed emergency repair of damaged floor in small gym. Complete repair scheduled for summer.
- Continuing to repair/replace lights out on campus to make travel safer for students.
- Hooked up electrical for short throw projectors in R101 and R119.
- Coordinated remodel of F100 and B100 at CEC. Paint, carpet and electrical completed.
- Installed carpet and new furniture in "The Spot."
- New furniture in H104, H105, R307, R303, D102, D108, A106.
- Installed 20 outlets in T machine shop with delineated flooring addition and compressed air lines for new machines.
- Re-routed electrical in Fashion Lab to accommodate new machines.
- Assisted with installation of new work benches in A214 for engineering student use.
- Coordinated removal of underground waste tank in automotive. Replaced with above ground tank.
- Coordinated repair of elevator in D building. Difficult situation.